
TS16: Communication error between master and slave unit (for twins system) Diagnosis and Solution

Description: When set in twins system, master unit and slave unit cannot be recognized normally.

Recommended parts to prepare:

- Connection wires
- Indoor PCB

