
TS41: Communication malfunction between adapter board and outdoor main control board diagnosis and solution

Description: If outdoor PCB does not receive feedback from adapter board.

Recommended parts to prepare:

- Connection wire
- Adapter PCB
- Outdoor PCB

Troubleshooting and repair:

