RIZQ VEHICLE INSPECTION

Pre-Purchase Vehicle Inspection Report

2020 Audi Q7 Prestige quattro

Report ID **JOB 4455** · Report Date Sep 27, 2026 · rizqvehicleinspection.com

88
VERY GOOD
RIZQ INSPECTION SCORE

13/15	45/45	28/30
Vehicle Representation	Overall Condition	Safety
Very Good	Excellent	Excellent

RIZQ VERDICT
BUY

TOP FINDINGS
- Front bumper — light scuffing at the lower corner with displaced air inlet trim
- No diagnostic trouble codes; engine and transmission perform normally
- Tires at 10/32" all around; brakes normal

REPAIR ESTIMATE
$450
Labor at $80/hr. Costs may vary depending on the shop chosen.

VEHICLE INFORMATION

Year	2020	**VIN**	WA1VXAF72LD011827
Make	Audi	**Mileage**	98,612 mi
Model	Q7	**Build Date**	06/2020
Trim	Prestige quattro	**Client**	—
Drivetrain	quattro AWD	**Location**	—
Transmission	Automatic	**Service**	Pre-Purchase Inspection

VERIFICATION

VERY GOOD

Item	Present	Details
Owner's Manual	Yes	
Service History	Yes	
Maintenance Records	Yes	
Last Oil Change	Yes	Documented
CARFAX Report	No	Not provided
Ignition Keys	Yes	1
Key FOBs	Yes	1
VIN Match (OBD scan)	Pass	WA1VXAF72LD011827

EXTERIOR — EXCELLENT

Panel	Condition	Panel	Condition
Front Bumper	Minor Scuffing / inlet trim	Rear Bumper	Normal
Left Front Fender	Normal	Right Front Fender	Normal
Driver Front Door	Normal	Passenger Front Door	Normal
Driver Rear Door	Normal	Passenger Rear Door	Normal
Left Quarter Panel	Normal	Right Quarter Panel	Normal
Hood	Normal	Liftgate	Normal
Roof / Panoramic Glass	Normal	Headlights / Taillights	Normal
Glass / Windshield	Normal	Wheels	Normal

Front bumper has light scuffing at the lower corner, and the air inlet trim insert at that corner is displaced/broken. All other panels are clean.

INTERIOR — EXCELLENT

Area	Condition	Notes
Driver Seat	Normal	
Passenger Seat	Normal	
Rear Seats	Normal	
Dashboard / Virtual Cockpit	Normal	
Center Console & Armrest	Normal	
Headliner / Panoramic Roof	Normal	
Seatbelts	Normal	
Electronics & Controls	Normal	All functional
SRS / Airbag System	Normal	No warning lights
Odor	Normal	Clean

MECHANICAL — EXCELLENT

Engine	Normal — Runs smooth, sounds normal
Transmission	Normal — Engages and shifts properly
quattro AWD	Normal
Leaks	Normal — No leaks observed
Cooling System / Fans	Normal
Exhaust	Normal
Suspension	Normal
Battery — Idle	12.9V Normal
Charging — Running	14.6V Normal

FLUID LEVELS

Engine Oil	Transmission Fluid	Engine Coolant	
FULL · NORMAL	FULL · NORMAL	FULL · NORMAL	
Brake Fluid	Power Steering Fluid	Washer Fluid	
FULL · NORMAL	FULL · NORMAL	FULL · NORMAL	

TIRES & BRAKES — EXCELLENT

10/32"	10/32"	10/32"	10/32"
Driver Front	Passenger Front	Driver Rear	Passenger Rear

Tire Brand	Goodyear
Tire Size	285/45R20
Minimum Recommended Tread	4/32"
Brakes (all four positions)	Normal

DIAGNOSTICS — EXCELLENT

OBD VIN Scan	Pass
DTC Status	No Codes
Readiness Monitors	Pass

ROAD TEST — EXCELLENT

Test Drive Completed	Yes
Acceleration	Normal
Braking	Normal
Steering	Normal
Transmission Shifting	Normal
Cruise Control	Normal
A/C & Heating	Normal
Noise / Vibration	Normal

The engine sounded normal and the transmission engaged and shifted properly. No issues noted.

PRICE & VALUE

ASKING PRICE	J.D. POWER AVG. RETAIL	J.D. POWER AVG. TRADE-IN
Not provided	**$20,153**	**$15,500**

SUGGESTED OFFER RANGE
$18,500 – $19,700

Range reflects J.D. Power average retail adjusted for the $450 repair estimate and expired factory warranty.

OPEN RECALLS

Campaign	Component	Description	Status
20V-658 (Audi 70H8)	Body — C-pillar	C-pillar padding may not absorb enough impact in a crash	Check VIN
Audi 69BV	Airbag control module	Front passenger airbag second stage may deploy too quickly; software update	Check VIN
Audi 20DR	Fuel pump	Internal fuel pump component may break, causing pump failure	Check VIN
Audi 90N7	Model-specific campaign	Applies to certain 2020 Q7 vehicles	Check VIN
Audi 90TV	Model-range campaign	Applies to certain 2019–2026 Audi vehicles	Check VIN

Campaigns listed apply to this model year. Open/completed status is confirmed by VIN with Audi (1-800-253-2834) or at nhtsa.gov/recalls; recall repairs are free of charge.

REMAINING WARRANTY

Coverage	Term	Remaining
New Vehicle Limited (incl. powertrain)	4 yr / 50,000 mi	Expired
Corrosion / Perforation	12 yr / unlimited mi	Active ~5–6 years remaining
Federal Emissions	8 yr / 80,000 mi	Expired

Estimated from 06/2020 build date and current mileage.

UPCOMING MAINTENANCE — NEXT 12 MONTHS

Item	Interval	Status
Engine oil & filter	10,000 mi / 12 mo	Due
Tire rotation	10,000 mi	Due
Cabin air filter	20,000 mi	Due
Brake fluid flush	24 mo	Upcoming
Engine air filter	60,000 mi	Upcoming
Spark plugs	60,000 mi	Upcoming

INSPECTOR COMMENTS

Car is in excellent condition. Minor damage to the front bumper only; all other panels, the interior, tires and brakes are in excellent order.

SUMMARY

Overall: Very Good (88/100). This Q7 presents in excellent overall condition. The scan returned no trouble codes, the engine and transmission performed normally on the road test, all fluids are full, the charging system is normal, tires measure 10/32" at all four positions and brakes are normal. The interior is clean with no wear or damage. The only finding is light scuffing at the lower front bumper corner with a displaced air inlet trim insert.


RIZQ recommends this vehicle for purchase.

DAMAGE DOCUMENTATION



1 · Front Bumper — Minor
Light scuffing at the lower corner; air inlet trim insert displaced/broken. Estimate covers R&I bumper cover, replace inlet trim insert and spot refinish.

PHOTO DOCUMENTATION — EXTERIOR













PHOTO DOCUMENTATION — WHEELS & TIRES








PHOTO DOCUMENTATION — INTERIOR














PHOTO DOCUMENTATION — ENGINE, DIAGNOSTICS & LABELS







PHOTO DOCUMENTATION — UNDERBODY



J.D. POWER (NADA) VALUES

2020 Audi Q7 Utility 4D Premium Plus 45 AWD — values at typical mileage.

Value Type	Low	Average	High
Retail — Buy from Dealer (avg. price paid)	$19,220	$20,153	$21,199
Trade-In	$13,500	$15,500	$17,000

Retail figures based on 3 transactions.