SOURCING PRO

Your Quality Partner In The Factory

REPORT #:PJ20260711

INSPECTION REPORT

General Information			
From :	Sourcing pro	To Client:	N/A
Contact:	Jack.Zhang	Contact:	Tom rijnen

Product Description	Electric Toothbrush
Item number	N/A
P/O number	N/A
Supplier name	SANMIN ZHIJIAN BAMBOO CO.,LTD
Factory Name	SANMIN ZHIJIAN BAMBOO CO.,LTD
Inspection location	SANMIN,FUJIAN,CHINA.
Inspector name	Mike Huang
Inspection date	July 11,2021



	PASS	FAIL	PENDING	NOT APPLICABLE	Remark
A: Quantity Available	☒	☐	☐	☐	1
B: Style and Color	☒	☐	☐	☐	2
C: Workmanship	☐	☐	☒	☐	3,4
D: On Site Test	☐	☐	☒	☐	5,6,8
E: Packing Method	☐	☐	☒	☐	7
CONCLUSION	**PENDING**				


Remarks

1. All items were produced but not packed into export cartons.

2. No approval sample was provided for inspection, actual style as below.



3. 30% samples were found poor painting at bottom  
4. All defectives we found during inspection were shown to the factory. The inspector advised the factory to fix all defectives asap.
5. Factory didn't allow us to conduct carton drop test.
6. Customer does not provide the product measurement tolerance range. Please refer to the data measurement section
7. No any shipping mark/white box and package method were provided by client or factory for reference.
8. Factory had no equipment to do battery capacity/ working current and voltage test. And factory did not allow us to disassemble the brush for internal check.

Inspector(s)	Mike Huang	Date	2026-07-11
Factory Representative		Date	2026-07-11
Report Reviewer(s)	Jack Zhang	Date	2026-07-12

SOURCING PRO

Your Quality Partner In The Factory

REPORT #:PJ20260711

A: Quantity Available

Po number	Item Number	Order Qty	Shipment Qty / Cartons		Available Qty / Cartons		Packed Qty / Cartons		Sample Size Qty / Cartons	
N/A	N/A	500	500	12	500	0	42	1	500	/
TOTAL		500	500	12	500	0	42	1	500	/
Comments:N/A										

B:Style and Color

☒ No sample ☐ Supplier sample ☐ Client sample

Supplementary information: ☒ Photo ☐ Purchase order ☐ Specification ☒ Others

	CHECK POINTS	RESULT	COMMENTS
1	Against product information on PO	☐ Pass ☐ Fail ☐ Pending	
2	Against product Specifications/Drawings /Photos	☐ Pass ☐ Fail ☒ Pending	
3	Against submitted Samples/ Color Swatch	☐ Pass ☐ Fail ☒ Pending	Remark 2
4	Against instruction manual/ other information on packaging/ product.	☒ Pass ☐ Fail ☐ Pending	
Comment: N/A			

C:Workmanship

7 % of defective product Sample Size: 500pcs	ANSI / ASQC Z1.4 (MIL – STD – 105 E) Sampling Plan: Single Sampling Plan: General Level II Acceptable Quality Level (AQL): Critical: 0 Major: 2.5 Minor: 4.0 A Critical Defect = FAIL

	Defect Description	Critical	Major	Minor
ITEM # Electric Toothbrush	Button downfaulted	0	2	0
	Poor painting	0	0	2
	Scratched mark	0	0	1
	Missing painting (white dot)	0	0	30
	Number of Defects Found:	0	2	33
	Number of Defect Allowed:	/	/	/
	Result:	/	/	/
Comment: N/A				

D:On Site Test			
Test item	Samples Size	Criteria	Result
Scan the barcode	5 samples	Check scanned no. to match the printed no. on the barcode. Also check the barcode no. to match with the requirement.	N/A
Carton assortment	2 cartons	According to PO/Specification, check the assortment of each carton was conformed to the requirement.	☒Pass ☐Fail ☐Pending
Product measurement	5 samples	According to PO/Specification, check if the item dimension and weight was conformed to the requirement.	☐Pass ☐Fail ☒Pending
Carton dimension	2 cartons	According to PO/Specification, check if the carton dimension was conformed to the requirement.	☐Pass ☐Fail ☒Pending
Carton G.W	2 cartons	According to PO/Specification, check if the carton gross weight was conformed to the requirement.	☐Pass ☐Fail ☒Pending
Carton drop test	1 carton	ISTA-1A drop test is required at outer level for all products unless otherwise specified. One corner,3 angles, and 6 faces.	☐Pass ☐Fail ☒Pending
Assembly Check	500pcs	According to instruction manual or specification.	☒Pass ☐Fail ☐Pending
General Function check	500pcs	-Verify all functions against available product specification, user manual and information on gift box. - If no notice available, use common sense to check the main function.	☒Pass ☐Fail ☐Pending
Moisture Content Check for wooden part	5 samples /item	General requirement is 8%~12% (Actual finding: 8.3,10.0,10.1,10.4,11.5%)	☒Pass ☐Fail ☐Pending

Data measurement -1				
Item #	Product size(cm)		Product weight(g)	
	Requirement	Actual finding	Requirement	Actual finding
Electric Toothbrush	/	24.5x3.0cm	/	115g

Data measurement -2				
Item #	Unit package		Master carton	
	Gross weight(g)	Dimension(cm)	Gross weight(kg)	Dimension(cm)
Electric Toothbrush	180g	9.5x23.3x3.5cm	8.15kg	48x30x26.5cm




E: Packing Method		
Outer packing	Corrugated Paper Plies:	☐Single Wall ☒Double Wall ☐Triple Wall
	Fastening:	☐Metal Staples ☒Glue
	Sealed by:	☐Kraft Tape ☐Green Opaque Gummed Tape ☒Transparent Gummed Tape
	Strapping:	☐Nylon Band ☒No
Outer packing quantity	42sets per outer carton.	
Inner packing	N/A	
Unit packing	Each into PVC box, then into a white box.	
Comments : N/A		






Photos attachment

	
1. Inspector in the factory gate	2. Goods storage
	
3. Goods storage	4. Goods storage
	
5. Carton view	6. Carton open

	
7. 5-ply	8. Packing view
	
9. White box view	10. White box view
	
11. White box view	12. White box view

	
13. White box view	14. White box view
	
15. White box view	16. White box view
	
17. White box view	18. Unit packing view


	
19. Unit packing view	20. Unit packing view
	
21. Instruction manual	22. Instruction manual
	
23. Instruction manual	24. Instruction manual

	
25. Instruction manual	26. Instruction manual
	
27. Instruction manual	28. Instruction manual
	
29. Instruction manual	30. Instruction manual


	
31. Instruction manual	32. Instruction manual
	
33. Product view	34. Product view
	
35. Product view	36. Product view

	
37. Product view	38. Product view
	
39. Product view	40. Product view
	
41. Product view	42. Product view

	
43. Product view	44. Product view
	
45. Product view	46. Product view
	
47. Product view	48. Product view

	
49. Product view	50. Product view
	
51. Product view	52. Product view
	
53. Product view	54. Product view

	
55. Product view	56. Product view
	
57. Product view	58. Product view
	
59. Product view	60. Product view



	
61. Product view	62. Product view
	
63. Product view	64. Product view
	
65. Product view	66. Product view

	
67. Product view	68. Product view
	
69. Function check	70. Function check
	
71. Function check	72. Function check


	
73. Function check	74. Function check
	
75. Function check	76. Function check
	
77. Function check	78. Function check


	
79. Function check	80. Water wash test
	
81. 3M test	82. Rubbing test
	
83. Moisture content test	84. Moisture content test

	
85. Moisture content test	86. Moisture content test
	
87. Moisture content test	88. Size check
	
89. Size check	90. Size check

	
91. Size check	92. Size check
	
93. Size check	94. Size check
	
95. Size check	96. Size check

	
97. Size check	98. Size check
	
99. Product weight check	100.Product weight check
	
101.Size check	102.Size check

	
103.Size check	104.Size check
	
105.Size check	106.Size check
	
107.Carton weight check	108.Carton weight check

	
109.Size check	110.Size check
	
111.Size check	112.Size check
	
113.Size check	114.Unit weight check

	
115. Poor painting on bottom-30%	116.Poor painting on bottom-30%
	
117.Poor painting on bottom-30%	118.Poor painting on bottom-30%
	
119.Poor painting on bottom-30%	120.Poor painting on bottom-30%

	
121.Defect: Button downfaulted-Major	122.Defect: Button downfaulted-Major
	
123.Defect: Poor painting on surface-Minor	124.Defect: Poor painting on surface-Minor
	
125.Defect: Scratched mark on surface-Minor	126.Defects: Missing painting(white dot)-30pcs

	
127.Defect: Missing painting(white dot)-30pcs	128.Defect: Missing painting(white dot)-30pcs
	
129.Defect: Missing painting(white dot)-30pcs	130.Defect: Missing painting(white dot)-30pcs
	
131.Defect: Missing painting(white dot)-30pcs	132.Defect: Missing painting(white dot)-30pcs

	
133.Defect: Missing painting(white dot)-30pcs	134.Defect: Missing painting(white dot)-30pcs

The above reflects our findings at time and place of inspection. This report does not relieve sellers/suppliers from their contractual obligations regarding quantity and/or quality of this delivery. This report is issued without prejudice to liability and the information contained herein is to the best of our knowledge and belief, true and correct. This document shall not be reproduced either in full or in part except with written approved by the Authorized Representative of Sourcing pro.

**********THE**********END**********