
TS43: Communication error between wired controller and indoor unit Diagnosis and Solution

- **Description:** If Indoor PCB does not receive feedback from wired controller, the error displays on the wired controller

Recommended parts to prepare:

- Connection wires
- Indoor PCB
- Wired controller

Troubleshooting and repair:

