
TS18: Outdoor unit malfunction Diagnosis and Solution

Description: The indoor unit detect the outdoor unit is error.

Recommended parts to prepare:

- Outdoor unit

Troubleshooting and repair:

