

RIZQ Vehicle Inspection

Pre-Purchase Vehicle Inspection Report

Confidential — Issued to Authorized Client Only | www.rizqinspections.com

REPORT ID

JOB 4455

RIZQ INSPECTION SCORE



13/15



Confirmed

Vehicle Representation

45/45



Excellent

Overall Condition

28/30



Excellent

Safety

RIZQ VERDICT

BUY

Front Bumper Minor Damage

Estimated repair cost: \$0

YOUR VEHICLE

Year	2020	Make	Audi
Model	Q7	Type	Auto
VIN	WA1VXAF72LD011827	Package	—
Mileage	98612 mi	Service	Inspection Only
Location	—, —	Inspection Date	—
Client	—	Inspector	—

VERIFICATION

Documentation

ITEM	PRESENT	ADDITIONAL DATA
Owner's Manual	Yes	
Service History	Yes	
Last Oil Change	Yes	See inspector notes
Maintenance Record	Yes	
CARFAX Report	No	
Ignition Keys	Yes	1
Key FOBs	Yes	1

TECH NOTES

VEHICLE INFO

VIN	WA1VXAF72LD011827
Make/Model	AUDI Q7
Year	2020
Trim	quattro Prestige
Mileage	98612

EXTERIOR PANELS

Front Bumper	Minor Damage
Rear Bumper	No Damage
Left Front Fender	No Damage
Right Front Fender	No Damage
Driver Front Door	No Damage
Driver Rear Door	No Damage
Passenger Front Door	No Damage
Passenger Rear Door	No Damage
Left Quarter Panel	No Damage
Right Quarter Panel	No Damage

INTERIOR	
Driver Seat	No Damage
Passenger Seat	No Damage
Rear Seats	No Damage
Dashboard	No Damage
Center Console	No Damage
Seatbelt Condition	Good
Odor	Clean

MECHANICAL	
Engine	Running Smooth
Transmission	Shifting Normal
Leaks	

FLUID LEVELS	
Engine Oil	Full
Transmission Fluid	Full
Engine Coolant	Full
Brake Fluid	Full
Power Steering	Full
Washer Fluid	Full

BATTERY VOLTAGE	
Battery Idle	12.9V
Battery Running	14.6V

TIRES & BRAKES	
Tire Brand	Goodyear
Tire Size	285/45r20
Driver Front Tread	10/32
Passenger Front Tread	10/32
Driver Rear Tread	10/32
Passenger Rear Tread	10/32
Tire Condition	All Good
Brakes	Normal

DIAGNOSTICS	
OBD VIN Scan	Pass
DTC Status	No Codes Present
OBD Codes	Clear

ROAD TEST	
Acceleration	Normal
Braking	Normal
Steering	Normal
Noise	

SUMMARY	
Overall Rating	Fair
Key Issues	None noted
Inspector Comments	

CONDITION

1 Deficiency Reported — See Exterior Section Below

Exterior Panels

PANEL	CONDITION	PANEL	CONDITION
Front Bumper	Minor Damage, Very Good	Rear Bumper	No damage noted
Left Front Fender	No damage noted	Right Front Fender	No damage noted
Driver Front Door	No damage noted	Driver Rear Door	No damage noted
Passenger Front Door	No damage noted	Passenger Rear Door	No damage noted
Left Quarter Panel	No damage noted	Right Quarter Panel	No damage noted
Hood	No damage noted	Liftgate / Spoiler	No damage noted
Roof / Panoramic Glass	No damage noted	Headlights / Taillights	No damage noted
Glass / Windshield	No damage noted	Wheels	No damage noted

Note: Front Bumper Minor Damage Minor damage to the front bumper light scuffing only..

Interior			
Interior Condition Assessment			
AREA	CONDITION	NOTES	
Steering Wheel	Good		
Dashboard / Instrument Panel	No Damage		
Front Seats	No Damage		
Rear Seats	Good		
Center Console & Armrest	No Damage		
Headliner	Good		
Trunk / Cargo Area	Good		
Electronics & Controls	Functional		
SRS / Airbag System	Good		


SAFETY — TIRES & BRAKES

Tire Specifications

	Driver Front	Passenger Front	Driver Rear	Passenger Rear
Brand	Goodyear	Goodyear	Goodyear	Goodyear
Model				
Size	285/45r20	285/45r20	285/45r20	285/45r20



NOTICE: Tires should be replaced when tread depth falls below 4/32". Inspect regularly for uneven wear. Brake pads should be replaced when thickness falls below 3mm and at every 50–60k mile interval.



ENGINE

Battery Voltage

12.9V
IDLE VOLTAGE
Ideal > 12.4V

14.6V
RUNNING VOLTAGE
Ideal 13.5V–14.8V | Alternator

SUPPLEMENTAL CHECKS

Fluid Levels		
FLUID	LEVEL / STATUS	NOTES
Engine Oil	FULL	Full
Transmission Fluid	FULL	
Engine Coolant	FULL	Full
Brake Fluid	FULL	
Power Steering Fluid	FULL	
Washer Fluid	FULL	

Scan Tool Diagnostics

DIAGNOSTIC ITEM	RESULT
VIN Scan Confirmation	PASS
Diagnostic Trouble Codes (Active)	CLEAR
OBD-II Readiness Monitors	READY

DRIVABILITY / ROAD TEST

OVERALL IMPRESSION

The engine sounded normal, the transmission engaged and shifted properly. No issues noted.

CHECK ITEM	STATUS	TECH COMMENTS
Security & Remote	OK	
Test Drive Completed	Yes	
Engine Operation	OK	Running Smooth
Transmission	OK	Shifting Normal
Transfer Case / AWD / 4x4	OK	
Cruise Control	OK	
Brakes	OK	
Steering	Full	
Driving NVH	=== SUMMAR	
Suspension	OK	
Odor & Leak Check	=== FLUID	=== FLUID LEVELS ===
Cooling Fans	OK	
A/C & Heating	OK	
Exhaust	OK	

REMAINING WARRANTY

COVERAGE	TERM	ESTIMATED REMAINING
Basic / Bumper-to-Bumper	3 yr / 36,000 mi	Expired
Powertrain Limited Warranty	5 yr / 60,000 mi	Expired
Corrosion / Perforation	5 yr / 100,000 mi	Expired
Emissions Control (Federal)	8 yr / 80,000 mi	Expired

Estimated from in-service date and current mileage.

UPCOMING MAINTENANCE — NEXT 12 MONTHS

ITEM	INTERVAL	STATUS
Engine oil and filter	7,500 mi / 6 mo	NEXT SVC
Tire rotation and inspection	7,500 mi / 6 mo	NEXT SVC
Cabin air filter	20,000 mi / 24 mo	NEXT SVC

FOCUS AREAS

Focus Area 1	
Area	Front Bumper
Customer Request	Minor Damage
Issue Found?	No
Tech Comments	Minor damage to the front bumper — light scuffing only.

ADMIN REVIEW NOTES

Car in excellent condition. Minor damage to the front bumper only all other panels, the interior, tires and brakes are in excellent order.

SUMMARY — EXCELLENT

OVERVIEW

Inspected at the listed location under the selected package. This vehicle presents in excellent overall condition. Findings are limited to minor damage.

PAINT & BODY

The only exterior finding is Minor damage to the front bumper light scuffing only..

INTERIOR

All seating, dash, controls, and electronics are in good working order and the cabin is clean.

TIRES & BRAKES

Tires and brakes were checked at all four positions and are documented in the Safety section above.

DIAGNOSTICS

The OBD-II scan and diagnostic results are documented in the Diagnostics section above.

ROAD TEST

Road test results acceleration, braking, and steering are documented in the Drivability section above.


UNDERBODY

Underbody, suspension, and drivetrain components were inspected and are documented in the Mechanical section above.

CONCLUSION

Findings are limited to 1 item, with an estimated repair cost of \$0. RIZQ recommends this vehicle for purchase.


VEHICLE DAMAGE DIAGRAM



- 1. Front Bumper— Very Good

PHOTO DOCUMENTATION

Exterior, Wheels & Tires




Interior





EV Compartment, Diagnostics & Brakes



Underbody & Suspension



Additional Photos





2020 AUDI Q7

Utility 4D Premium Plus 45 AWD Values

PRICING & VALUES

Prices shown for the used **2020 Audi Q7 Utility 4D Premium Plus 45 AWD** with typical miles are what people paid to buy this vehicle or what people received when trading in this vehicle at a dealer. **Edit options.**

BUY FROM DEALER

Prices shown are what people paid including dealer discounts. Taxes and fees (title, registration, license, document, and transportation fees) are not included.

Buy from Dealer

[Buy Certified from Dealer](#)



Average Price Paid

\$20,153



80% of People Paid

\$19,220 - \$21,199

Data from 3 transactions - Updated 04/05/26



Sign in to jdpower.com with Google

Continue

ESTIMATED TRADE-IN VALUE

Prices shown are what people received from a dealer for their trade-in vehicle by condition.

See definitions.

Base Price	\$13,500
Mileage and Options	\$0
Low ⓘ	\$13,500
Base Price	\$15,500
Mileage and Options	\$0
Average ⓘ	\$15,500
Base Price	\$17,000
Mileage and Options	\$0
High ⓘ	\$17,000

The values are not for commercial use.

Looking for values for your business? **JD Power Valuation Services** can help.

2020 AUDI Q7 PHOTOS AND VIDEOS

Selected Trim: Utility 4D Premium Plus 45 AWD

All Interior Photos

All Exterior Photos

[SEE 16 PHOTOS AND VIDEOS >](#)

CAR LOAN CALCULATOR

Monthly Payments

[What Can I Afford](#)

Car Price
\$20,153

Trade-In Value
\$0

Interest Rate (%)
3.95

Down Payment
\$0

Sales Tax (%)
California 7.25%

Loan Term (Months)
60

\$397.57 per month

Actual price and payments may be different due to local rebates, specials, fees, and credit qualifications. Consult your dealer for actual price, payments, and complete details. [View Disclosures](#)

TOP ALTERNATIVES

**2020 JAG
PACE**

87

People are Paying
\$13,838 - \$22,242

**2020 BUICK
ENVISION**

86

People are Paying
\$16,538 - \$23,798

**2020 NISSAN
ARMADA**

86

People are Paying
\$18,838 - \$31,45



Catch up on our latest [2020 Audi Q7 Expert Review >](#)