

Field Rep Site Visit KPI Sheet

Basic Information

Date: 4-28-26

Rep Name: _____

Location Name: North Side High School

Location Address: _____

Visit Type: (Routine) Follow-up / Issue Response / Audit)

Operational KPIs

Overall Site Condition (1-5):

Service Quality (1-5):

Vendor/Tech Performance (1-5):

Client Feedback (1-5):

Complaints/Issues:

Side walk grass coming
up in cracks need mowed
up.

lawn looks good. Just need
side walk and fence line sprayed
for weeds
B. Chandler

Maintenance & Repairs

General Repairs: (1-5) N/A

Lawn Care / Landscaping (1-5)

Snow/Ice (if applicable):

N/A

Photos & Documentation

Photos Taken (Yes No)

Number of Photos: N/A

Key Issues Captured: NA

Summary Scores

Overall Site Score: _____

Maintenance Score: _____

Service Quality Score: _____

Rep Comments

General Observations:

Recommendations: _____

Follow-up Required (Yes/No):

Manager Review

Site Rep: W. J. L. L.

Reviewed By Nahb Song
Comments: overall good job

Comments:

Overall good job